



# Arkansas Architectural Resources Survey Form

**ARKANSAS  
HISTORIC  
PRESERVATION  
PROGRAM**

- 1. Resource Number:
- 2. NR Eligibility:   
 01-Eligible 02-Ineligible 03-Listed 05-Arkansas Register Listed  
 06-Contributing in a Listed District 08-Contributing in a Potential District
- 3. Contributing/Non-Contributing:
- 4. Destroyed: (Y or N)  Date:

### Above for AHPP Use Only

#### Survey Data

- 5. Date Recorded:  /  /
- 6. Recorded By: S. Elizabeth Valenzuela  
Miriam Tworek-Hofstetter
- 7. Survey Number:

- 8. Historic Name: Hattie L. Bew Rooming House
- 9. Alternate Name: Baxter Hotel
- 10. District Name: Pleasant Street Historic District
- 11. Quad Map:
- 12. Geographic Location: S  T  R
- 13. UTM Coordinates: Z  E  N
- 14. Town/Nearest Community: Hot Springs
- 15. Street Address/Directions to Resource: 221 Cottage Street

- 16. Owner: Hot Springs Advertising & Promotion Commission
- 17. Owner Address: 134 Convention Blvd., Hot Springs, AR 71901
- 18. Owner Phone Number: (  )  -
- 19. Informant Name & Phone Number: \_\_\_\_\_  
(  )  -

#### Descriptive Data

- 20. Threats to Property:  Other: demolished
- 1-None/Property Stable    2-Neglect/Deterioration    5-Private Development    6-Extractive Industry  
 7-Urban Encroachment    8-Government Activity    9-Other

21. Historic Use: 

			0
--	--	--	---

 Other: \_\_\_\_\_

22. Present Use: 

			0
--	--	--	---

 Other: demolished

0101-Single Family Dwelling    0102-Multi-Family Dwelling    0301-General Retail Store    0308-Bank    0309-Office  
0401-Church    0601-School    1200-Cemetery    9800-Structure Abandoned/Unoccupied.    9900-Other

23. Setting: 

5
---

 Other: 0

1-Rural, Undisturbed    2-Rural, Built-Up    3-Urban Encroachment    4-Small Town    5-Urban    9-Other

24. Total Number of Site Features: 

0	0	0
---	---	---

 \_\_\_\_\_  
(e.g. concrete walls, ponds, statuary) \_\_\_\_\_

25. Total Number of Ancillary Structures: 

0	0	0
---	---	---

 \_\_\_\_\_  
(e.g. outbuildings, etc.) \_\_\_\_\_

26. Style Influence: Primary: 

0	0
---	---

 Secondary: 

0	0
---	---

 Other: \_\_\_\_\_

01-Plain/Traditional    04-Greek Revival    05-Italianate    09-Queen Anne/Eastlake    10-Classical Revival  
15-Craftsman    18-Art Deco    19-Art Moderne    21-Standard Commercial    19<sup>th</sup> Century  
22-Standard Commercial    20<sup>th</sup> Century    24-English Revival    25-Colonial Revival    26-American Foursquare  
29-Ranch    33-Mixed Masonry    35-Folk Victorian    99-Other

27. Plan: 

0	0
---	---

 Other: \_\_\_\_\_

01-One Room/Single Pen    03-Double Pen    04-Dogtrot    05-Single Pile w/ Central Hall  
17-Shotgun    99-Other

28. Height: 

0	0
---	---

 Other: \_\_\_\_\_

01-One    02-One & One-Half    03-Two    04-Two & One-Half    95-Varied    99-Other

29. Basement/Cellar: 

0
---

 Other: \_\_\_\_\_

1-Full    2-Partial    3-No Cellar    8-Unknown    9-Other

30. Wings and/or Projections: A 

0	0
---	---

 B 

0	0
---	---

 C 

0	0
---	---

 Other: \_\_\_\_\_

01-Rear Shed    02-Rear L    03-Rear T    04-Side    11-Enclosed    12-Rear Room    99-Other

31. Construction: A 

0	0
---	---

 B 

0	0
---	---

 Other: \_\_\_\_\_

01-Log    06-Frame    08-Brick    10-Steel Frame    11-Concrete Block    12-Reinforced Concrete    99-Other

32. Original Wall Material: A 

0	0
---	---

 B 

0	0
---	---

 Other: \_\_\_\_\_

33. Present Wall Material: A 

0	0
---	---

 B 

0	0
---	---

 Other: \_\_\_\_\_

01-Log    02-Weatherboard    03-Novelty Siding    04-Board/Batten    05-Brick  
07-Stone    10-Stucco    12-Cut Stone    13-Field Stone    14-Asbestos  
16-Concrete Block    17-Wood Shingle    18-Cast Concrete    21-Horizontal Board    23-Vertical Board  
31-Vinyl Siding    32-Aluminum Siding    97-Unknown    98-Original Material    99-Other

34. Roof Types: A 

0	0
---	---

 B 

0	0
---	---

 C 

0	0	0
---	---	---

 Other: \_\_\_\_\_

01-Gable    02-Gable w/ Parapet    03-Clipped Gable    04-Gable on Hip    06-Hip    07-Pyramid  
08-Gambrel    09-Mansard    12-Flat    13-Flat w/ Parapet    14-Shed    99-Other

35. Roof Features (if present): A 

0	0
---	---

 B 

0	0
---	---

 Other: \_\_\_\_\_

01-Dormer(s)    02-Steeple    03-Cupola    04-Cresting    05-Clock Tower    07-Tower/Turret  
08-Belfry    10-Skylight    99-Other

36. Roof Materials: A 

0	0
---	---

 B 

0	0
---	---

 Other: \_\_\_\_\_

01-Wood    02-Asphalt Shingle    03-Metal    05-Tile    06-Tar Built-up    99-Other

37. Chimney Placement: A  B  C  D  Other: \_\_\_\_\_  
 1-Exterior End 2-Interior End 3-Other Exterior 4-Interior Central 5-Other Interior 9-Other
38. Chimney Materials: A  B  C  D  Other: \_\_\_\_\_  
 1-Brick 4-Cut Stone 5-Field Stone 6-Metal 9-Other
39. Foundation Type: A  Other: \_\_\_\_\_  
 1-Continuous 2-Piers 4-Enclosed Piers 9-Other
40. Foundation Materials: A  Other: \_\_\_\_\_  
 1-Wood Block 2-Stone 3-Brick 4-Cast Concrete 5-Concrete Block 9-Other
41. Porch Types: A  B  C  Other: \_\_\_\_\_  
 01-Full, Front 02-Three-quarter, Front 03-One-Bay, Central Front 05-Wrap-around  
 06-Awning 07-One-Half, Front 08-Recessed, Front 09-Side 15-Stoop 99-Other
42. Porch Height (Stories): A  B  C  D  Other: \_\_\_\_\_  
 1-One 2-One & One-Half 3-Two 4-Two & One-Half 9-Other
43. Porch Roof Types: A  B  C  D  Other: \_\_\_\_\_  
 1-Gable 2-Hip 3-Flat 4-Shed 5-Clipped Gable 6-Integral 9-Other
44. Porch Details: A  B  C  Other: \_\_\_\_\_  
 01-Chamfered Posts 02-Turned Posts 03-Columns 04-Balustrade 05-Wood Ornament  
 08-Columns on Piers 11-Posts 12-Iron Posts 13-Screened-in 14-Iron Railing 99-Other
45. Window Type(s): A  B  C  D  Other: \_\_\_\_\_  
 1-Double-hung 3-Casement 4-Stationary 6-Hopper 7-Awning 9-Other/Materials
46. Light Pane Arrangement: A  /  B  /  C  /
47. Condition:   
 1-Excellent 2-Good 3-Fair 4-Deteriorated 5-Ruin
48. Architectural Comments: Demolished

### Historic Data:

49. Architect: N/A
50. Builder: N/A
51. Construction Date:  C-circa D-date  0 Other: \_\_\_\_\_
52. Historic Context: Building demolished.
53. Ethnic Heritage: A  B  Other: \_\_\_\_\_  
 01-Asian 02-African American 03-European 04-Hispanic 05-Native American  
 06-Early American/Caucasian 99-Other
54. Please rate the level of significance of this property compared to others within survey area:   
 1-Very Significant 2-Moderately Significant 3-Significant Within a Group Context  
 4-Marginal 5-Non-Significant